

User's information

Safety gloves against chemical and mechanical risks

Manufacturer UVEX SAFETY Gloves GmbH & Co. KG

Elso-Klöver-Str. 6, 21337 Lüneburg Postfach 24 47 · 21314 Lüneburg

Germany

Type uvex rubiflex S - NB40S

Model 98902

Basic glove material cotton interlock **Available sizes** 8, 9, 10, 11 Tel.: +49 4131 9502-0 Fax: +49 4131 84338 Email: gloves@uvex.de Website: uvex-safety.de

Coating material Special NBR (nitrile

butadiene rubber)

Smallest packing unit 60 Pairs

Pictogram and performance levels

EN 374: 2003



JKL Performance level

n-heptane Class 6 (> 480 min)
Sodium hydroxide 40% Class 6 (> 480 min)
Sulphuric acid 96% Class 2 (> 30 min)

Pictogram and performance levels according to EN 374:2003 (lowest performance level: 1/highest performance: 6)

The sampling for penetration testing is made by general inspection level according to DIN 2859, part 1 with AQL 4.0.

<u>Please note:</u> The actual period of protection on the job is affected by many factors (temperature, abrasion, etc.) and can therefore differ from the performance level!

EN 388 : 2003



2 1 2 1 Performance levels

Puncture resistance
Tear resistance
Cut resistance

Pictogram and performance levels according to EN 388:2003 (highest performance level: 4/cut resistance: 5)

Abrasion resistance

All levels only apply to the coated areas of the glove.

EC notified body TÜV Rheinland LGA Products GmbH

Tillystraße 2 · 90431 Nürnberg

No.: 0197

Cleaning Cleaning only possible when not working with aggressive chemicals. Carefully rinse gloves

under lukewarm running water.

Storage Store in a dark, dry place.

Handling Thoroughly check before use on damage, defective gloves should not be used. All technical

data refers to the delivered state, unused and not stretched at ambient temperature (EN 374).

At expiration of the permeation time the glove must be disposed.

After contamination, a change of performance cannot be excluded.

We are not aware of any substances in this product that could cause an allergic reaction.

Warning Gloves should not be worn where there is a risk of being caught in moving machinery parts.