







-WATER RESISTAN COMFORT

FLEXIBLE

WARONA 5400







CHARACTERISTICS

- · Quality: 100% polyester with PU coating, 170 gr/m²
- \cdot Covered two-way zip with press studs and handy pull zipper
- · Fixed hood with drawstrings
- · Double storm flap
- · Wind cuffs on the sleeves
- · Adjustable leg cuffs with press studs
- · Elastic waist
- · High-frequency welded seams
- $\boldsymbol{\cdot}$ Wind- and waterproof

Article number: 2.45.400.00

SUITABLE FOR ACTIVITIES IN E.G.

- \cdot Construction
- · Shipbuilding
- ·Shipping
- · Industry
- · Transport & logistics
- · Agriculture

COLOUR

Navy blue

OTHER AVAILABLE COLOURS

Yellow (article number: 2.45.405.00) Green (article number: 2.45.415.00)

SIZES

S to 4XL incl.

PACKAGING

- 1 unit per polybag
- · 10 units per outer box

EN 343:2003+A1:2007



C E EN ISO 13688:2013




PRODUCT INFORMATION

SIZE	ARTICLE NO.	EAN CODE 1 ITEM (POLYBAG)	EAN CODE 10 ITEMS (OUTER BOX)
S	2.45.400.03	8718249032615	8718249032622
М	2.45.400.04	8718249032639	8718249032646
L	2.45.400.05	8718249032653	8718249032660
XL	2.45.400.06	8718249032677	8718249032684
XXL	2.45.400.07	8718249032691	8718249032707
3XL	2.45.400.08	8718249032714	8718249032721
4XL	2.45.400.09	8718249032738	8718249032745

WASHING INSTRUCTIONS





CLARIFICATION OF PICTOGRAMS

EN 343:2003+A1:2007 Protective clothing against rain

The EN 343:2003 standard specifies the requirements and test methods for clothing materials and seams which protect against precipitation (rain and snow), fog and ground humidity. For workwear that complies with the EN 343:2003 standard, water penetration resistance and water vapour permeability are of the greatest importance. These parameters are always stated next to the pictogram. The seams are watertight finished in accordance with the highest class.

EN 343:2003+A1:2007



- X = Class of water penetration resistance, ranging from class 1 to 3 (see label for correct class)
- Y = Class of water vapour permeability, ranging from class 1 to 3 (see label for the right class)

STORAGE CONDITIONS

The clothing should be kept in a clean, cool and dry place and not kept compressed in its original packaging. Do not expose the clothing to direct sunlight. Never store the clothing wet, always hang it to dry first. Make sure that the packaging and the garment are not damaged during shipping.

DECLARATION OF CONFORMITY

For a copy of the declaration of conformity, we refer you to the following link: www.oxxa-safety.com/doc

RELATED PRODUCTS



WALAKA 5200 Art. no. 2.45.200.00



Art. no. 2.45.300.00

YOUR SUPPLIER:

